

Message

---

**From:** Rumrill, Nancy [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=ECC4D19E0739473E8D3B141813288234-NRUMRILL]  
**Sent:** 12/6/2019 4:48:05 PM  
**To:** Richard Tremblay [RTremblay@tasekomines.com]  
**Subject:** RE: Annual Injection Well MIT Testing

Hi Richard,  
Please provide a diagram of the pressure testing configuration with the packers and tubing installed.  
Thanks, Nancy

---

*Nancy Rumrill (rumrill.nancy@epa.gov)  
Groundwater Protection Section (WTR-4-2)  
US EPA, Region IX  
75 Hawthorne St.  
San Francisco, CA 94105  
Phone (415) 972-3293*

---

**From:** Richard Tremblay <RTremblay@tasekomines.com>  
**Sent:** Friday, December 6, 2019 7:40 AM  
**To:** Rumrill, Nancy <Rumrill.Nancy@epa.gov>  
**Subject:** RE: Annual Injection Well MIT Testing

Hi Nancy,  
As requested please find attached as built drawings of the four injection wells. The mechanical testing procedure is also attached. Current schedule (subject to change) for the four wells is as follows:

- I-01: Monday Dec 9<sup>th</sup>
- I-02: Thursday Dec 12<sup>th</sup>
- I-03: Monday Dec 16<sup>th</sup>
- I-04: Thursday Dec 19<sup>th</sup>

Any other questions please let me know.  
Regards,  
Richard

**Richard Tremblay** Vice President Operations



Florence Copper Inc.  
1575 W. Hunt Highway Florence AZ USA 85132  
T 520-316-3710 F 520-374-3999  
E [rtremblay@tasekomines.com](mailto:rtremblay@tasekomines.com) Web [florencecopper.com](http://florencecopper.com)

---

**From:** Rumrill, Nancy <[Rumrill.Nancy@epa.gov](mailto:Rumrill.Nancy@epa.gov)>  
**Sent:** December 5, 2019 2:37 PM  
**To:** Richard Tremblay <[RTremblay@tasekomines.com](mailto:RTremblay@tasekomines.com)>  
**Subject:** RE: Annual Injection Well MIT Testing

Hi Richard,

Please provide a diagram of the well configuration and proposed procedures for the testing, as soon as possible. I also need to know when the testing will be for each well to coordinate with an ADEQ inspector to be present during part or all of the testing.

Thanks, Nancy

---

*Nancy Rumrill ([rumrill.nancy@epa.gov](mailto:rumrill.nancy@epa.gov))  
Groundwater Protection Section (WTR-4-2)  
US EPA, Region IX  
75 Hawthorne St.  
San Francisco, CA 94105  
Phone (415) 972-3293*

---

**From:** Richard Tremblay <[RTremblay@tasekomines.com](mailto:RTremblay@tasekomines.com)>  
**Sent:** Thursday, December 5, 2019 11:56 AM  
**To:** Rumrill, Nancy <[Rumrill.Nancy@epa.gov](mailto:Rumrill.Nancy@epa.gov)>  
**Subject:** Re: Annual Injection Well MIT Testing

Hi Nancy,

Yes I can confirm we are conducting mechanical integrity pressure testing of the four injection wells and all four will be completed over the next 9 days. I'll call you in about an hour when I'm in a good location.

Regards,  
Richard

Sent from my iPhone

On Dec 5, 2019, at 12:30 PM, Rumrill, Nancy <[Rumrill.Nancy@epa.gov](mailto:Rumrill.Nancy@epa.gov)> wrote:

Hi Richard,

Per our discussion, please confirm that your annual Part I Mechanical Integrity demonstration has been scheduled or conducted for each injection well pursuant to Permit condition Part II.E.3.b.i. The condition requires pressure testing for internal mechanical integrity in accordance with Paragraph II.E.3.a.i.A of the Permit. Please call me to discuss your test procedures and scheduling.

Thanks, Nancy

---

*Nancy Rumrill ([rumrill.nancy@epa.gov](mailto:rumrill.nancy@epa.gov))  
Groundwater Protection Section (WTR-4-2)  
US EPA, Region IX*

75 Hawthorne St.  
San Francisco, CA 94105  
Phone (415) 972-3293

---

**From:** Richard Tremblay <[RTremblay@tasekomines.com](mailto:RTremblay@tasekomines.com)>

**Sent:** Monday, November 25, 2019 10:02 AM

**To:** Rumrill, Nancy <[Rumrill.Nancy@epa.gov](mailto:Rumrill.Nancy@epa.gov)>

**Subject:** Annual Injection Well MIT Testing

Hi Nancy,

Further to our discussion on Friday I have confirmed a mechanical integrity test on the four injection wells were tested and passed as per the table below which was included in the 2019 Q1 reporting (Attachment 8).

Regards,

Richard

<image001.png>

Richard Tremblay , MBA, P. Eng.  
Vice President Operations



Taseko Mines Limited | 1040 - West Georgia, Suite 1500 Vancouver, BC V6E 4H1  
D +1-778-373-4573 T +1-778-373-4533 F +1-778-373-4534  
E [rtremblay@tasekomines.com](mailto:rtremblay@tasekomines.com) Web [tasekomines.com](http://tasekomines.com)

---

"Notice Regarding Transmission

This message is intended only for the person(s) to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is prohibited. Please notify us of the error in communication by telephone (778-373-4533) or by return e-mail and destroy all copies of this communication. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Taseko Mines Limited or any affiliated or associated company. The recipient should check this email and any attachments for the presence of viruses. Neither Taseko Mines Limited nor any affiliated or associated company accepts any liability for any damage caused by any virus transmitted by this email. Thank you."

---

"Notice Regarding Transmission

This message is intended only for the person(s) to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is prohibited. Please notify us of the error in communication by telephone (778-373-4533) or by return e-mail and destroy all copies of this communication. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Taseko Mines Limited or any affiliated or associated company. The recipient should check this email and any attachments for the presence of viruses. Neither Taseko Mines Limited nor any affiliated or associated company accepts any liability for any damage caused by any virus transmitted by this email. Thank you."

---

"Notice Regarding Transmission

This message is intended only for the person(s) to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is prohibited. Please notify us of the error in communication by telephone (778-373-4533) or by return e-mail and destroy all copies of this communication. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Taseko Mines Limited or any affiliated or associated company. The recipient should check this email and any attachments for the presence of viruses. Neither Taseko Mines Limited nor any affiliated or associated company accepts any liability for any damage caused by any virus transmitted by this email. Thank you."